Cutting Processes for Welding - WE106

Section: WE106 009261S Hillsboro
Credit Hours: 2.00
Course Description: Types of mechanical and thermal cutting equipment and processes used in the welding trade; safe and correct set up, operation and shut down of the Oxy-Fuel Cutting (OFC) workstation, Plasma Arc Cutting (PAC) workstation, and Carbon Arc Cutting with Air (CAC-A) workstations, safe and proper operation of a metal shear, iron worker type equipment, band saw, bench and angle grinders, and inspection of quality and tolerance of cuts according to industry standards.
WHEN Start Date: 08/27/2026 End Date: 11/23/2026
Days:
MR
7:00 AM - 9:30 AM
Campus: Hillsboro
Building: Hillsboro Welding
Room: HB001

INSTRUCTOR
JOSH LEWIS
BOOKS
Title: WELDING TOOL KIT
Author: HUTCHCC
Required: No