Cutting Processes for Welding - WE106

Section: WE106 009251S Hillsboro

Section Type: Lecture **Credit Hours:** 2.00

Course Description: Types of mechanical and thermal cutting equipment and processes used in the welding trade; safe and correct set up, operation and shut down of the Oxy-Fuel Cutting (OFC) workstation, Plasma Arc Cutting (PAC) workstation, and Carbon Arc Cutting with Air (CAC-A) workstations, safe and proper operation of a metal shear, iron worker type equipment, band saw, bench and angle grinders, and inspection of quality and tolerance of cuts according to industry standards.

WHEN Start Date: 08/25/2025 End Date: 11/20/2025

Days: MR

7:00 AM - 9:30 AM Campus: Hillsboro

Building: Hillsboro Welding

Room: HB001

INSTRUCTOR
JOSH LEWIS
BOOKS

Title: WELDING TOOL KIT

Author: HUTCHCC

Required: No