

Cutting Processes for Welding - WE106

Section: WE106 003192S Buhler

Section Type: Lecture

Credit Hours: 3.00

Course Description: Types of mechanical and thermal cutting equipment and processes used in the welding trade; safe and correct set up, operation and shut down of the Oxy-Fuel Cutting (OFC) workstation, Plasma Arc Cutting (PAC) workstation, and Carbon Arc Cutting with Air (CAC-A) workstations, safe and proper operation of a metal shear, iron worker type equipment, band saw, bench and angle grinders, and inspection of quality and tolerance of cuts according to industry standards.

Section Notes: Buhler High School Students only.

WHEN

Days: MTWRF

Times: 12:50 PM - 01:40 PM

Start Date: 01/13/2020

End Date: 05/14/2020

WHERE

Campus: Buhler

Building: Buhler High School

Room: BHHS01

INSTRUCTOR

CODY MCREYNOLDS

BOOKS

No textbooks for this course.